

AD-A086 696


NEW JERSEY DEPT OF ENVIRONMENTAL PROTECTION TRENTON  
NATIONAL DAM SAFETY PROGRAM. CLINTON RESERVOIR DAM (NJ 00314) P--ETC(U)  
APR 80 J P TALERICO

F/G 13/13

DACN61-79-C-0011  
NL

UNCLASSIFIED

1 of 1  
AD-A086 696



AL A 086896

**LEVEL**

①

PASSAIC RIVER BASIN  
CLINTON BROOK, PASSAIC COUNTY  
NEW JERSEY

# CLINTON RESERVOIR DAM

NJ 00314

DDC  
SELECTED  
SERIES

PHASE 1 INSPECTION REPORT  
NATIONAL DAM SAFETY PROGRAM



Approved for public release;  
distribution unlimited

DEPARTMENT OF THE ARMY

Philadelphia District  
Corps of Engineers  
Philadelphia, Pennsylvania

ORIGINAL CONTAINS COLOR PLATES: ALL DDC  
REPRODUCTIONS WILL BE IN BLACK AND WHITE.

APRIL 1980

DDC FILE COPY

80 7 18 071

SECURITY CLASSIFICATION OF THIS PAGE (When Data Entered)

REPORT DOCUMENTATION PAGE		READ INSTRUCTIONS BEFORE COMPLETING FORM
1. REPORT NUMBER NJ00314	2. GOVT ACCESSION NO. AD-A086896	3. RECIPIENT'S CATALOG NUMBER
4. TITLE (and Subtitle) <u>Phase I Inspection Report</u> National Dam Safety Program Clinton Reservoir Dam (NJ 00314) Passaic County, NJ River, Passaic, Clinton	5. TYPE OF REPORT & PERIOD COVERED 9 FINAL rept.	
7. AUTHOR(s) John P. Talerico	8. PERFORMING ORG. REPORT NUMBER 15	
9. PERFORMING ORGANIZATION NAME AND ADDRESS Fredric R. Harris Inc. 453 Amboy Ave. Woodbridge, NJ 07095	10. PROGRAM ELEMENT, PROJECT, TASK AREA & WORK UNIT NUMBERS	
11. CONTROLLING OFFICE NAME AND ADDRESS NJ Department of Environmental Protection Division of Water Resources P.O. Box CN029 Trenton, NJ 08625	12. REPORT DATE 14 Apr 1986	
14. MONITORING AGENCY NAME & ADDRESS (if different from Controlling Office) U.S. Army Engineer District, Philadelphia Custom House, 2d & Chestnut Streets Philadelphia, PA 19106	13. NUMBER OF PAGES 63	
15. SECURITY CLASS. (of this report) Unclassified		15a. DECLASSIFICATION/DOWNGRADING SCHEDULE
16. DISTRIBUTION STATEMENT (of this Report) Approved for public release; distribution unlimited.		
17. DISTRIBUTION STATEMENT (of the abstract entered in Block 20, if different from Report) 12/85		
18. SUPPLEMENTARY NOTES Copies are obtainable from National Technical Information Service, Springfield, Virginia 22151.		
19. KEY WORDS (Continue on reverse side if necessary and identify by block number) Dams Spillways Dam Safety Embankments Seepage National Dam Safety Program Structural analysis Clinton Reservoir Dam, N.J.		
20. ABSTRACT (Continue on reverse side if necessary and identify by block number) This report cites results of a technical investigation as to the dam's adequacy. The inspection and evaluation of the dam is as prescribed by the National Dam Inspection Act, Public Law 92-367. The technical investigation includes visual inspection, review of available design and construction records, and preliminary structural and hydraulic and hydrologic calculations, as applicable. An assessment of the dam's general condition is included in the report.		

NOTICE

THIS DOCUMENT HAS BEEN REPRODUCED  
FROM THE BEST COPY FURNISHED BY  
THE SPONSORING AGENCY. ALTHOUGH  
IT IS RECOGNIZED THAT CERTAIN POR-  
TIONS ARE ILLEGIBLE, IT IS BEING  
RELEASED IN THE INTEREST OF MAKING  
AVAILABLE AS MUCH INFORMATION AS  
POSSIBLE.



IN REPLY REFER TO  
NAPEH-H

DEPARTMENT OF THE ARMY  
PHILADELPHIA DISTRICT, CORPS OF ENGINEERS  
CUSTOM HOUSE—2 D & CHESTNUT STREETS  
PHILADELPHIA, PENNSYLVANIA 19106

Honorable Brendan T. Byrne  
Governor of New Jersey  
Trenton, New Jersey 08621

10 JUL 1980

Dear Governor Byrne:

Inclosed is the Phase I Inspection Report for Clinton Reservoir Dam in Passaic County, New Jersey which has been prepared under authorization of the Dam Inspection Act, Public Law 92-367. A brief assessment of the dam's condition is given in the front of the report.

Based on visual inspection, available records, calculations and past operational performance, Clinton Reservoir Dam, a high hazard potential structure, is judged to be in good overall condition. The dam's spillway is considered inadequate because a flow equivalent to 58 percent of the Probable Maximum Flood would cause the dam to be overtopped. To ensure adequacy of the structure, the following actions, as a minimum, are recommended:

a. The spillway's adequacy should be determined by a qualified professional consultant engaged by the owner using more sophisticated methods, procedures, and studies within six months from the date of approval of this report. Within three months of the consultant's findings, remedial measures to ensure spillway adequacy should be initiated.

b. The owner should develop an emergency action plan (if one is not already available) outlining actions to be taken by the operator to minimize downstream effects of an emergency and establish a flood warning system for the downstream communities within three months from the date of approval of this report.

c. The following remedial actions should be initiated within twelve months from the date of approval of this report:

(1) Observation wells or piezometers should be installed in the embankment and the spillway discharge channel to determine the location of the phreatic surface and the paths of the seepage observed.

(2) The flow of seepage should be monitored monthly to determine its volume and whether it presents a problem to the safety of the dam.

NAPEN-N

Honorable Brendan T. Byrne

(3) All trees and brush should be removed from the side slopes to avoid problems which may develop from roots. The embankment face should then be reseeded to develop a growth of grass for surface erosion protection.

(4) Remove vegetation from the downstream channel.

d. Within one year from the date of approval of this report, repair the crack across the spillway, replace the missing boulders in the right abutment masonry wall and regrout the wall.

e. Within two years from the date of approval of this report, consider providing additional low-level outlet facilities to decrease the draw down time.

f. Within one year from the date of approval of this report, the owner should develop written operating procedures and a periodic maintenance plan to ensure the safety of the dam.

A copy of the report is being furnished to Mr. Dirk C. Hofman, New Jersey Department of Environmental Protection, the designated State Office contact for this program. Within five days of the date of this letter, a copy will also be sent to Congressman Roe of the Eighth District. Under the provision of the Freedom of Information Act, the inspection report will be subject to release by this office, upon request, five days after the date of this letter.

Additional copies of this report may be obtained from the National Technical Information Services (NTIS), Springfield, Virginia 22161 at a reasonable cost. Please allow four to six weeks from the date of this letter for NTIS to have copies of the report available.

Accession For	
NTIS GRA&I	<input checked="checked" type="checkbox"/>
DDC TAB	<input type="checkbox"/>
Unannounced	<input type="checkbox"/>
Justification	
By _____	
Distribution/_____	
Availability Codes	
Dist.	Avail. for special
A	

MAPEN-N

Honorable Brendan T. Byrne

An important aspect of the Dam Inspection Program will be the implementation of the recommendations made as a result of the inspection. We accordingly request that we be advised of proposed actions taken by the State to implement our recommendations.

Sincerely,



JAMES G. TON  
Colonel, Corps of Engineers  
District Engineer

1 Incl  
As stated

Copies furnished:  
Mr. Dirk C. Hofman, P.E., Deputy Director  
Division of Water Resources  
N.J. Dept. of Environmental Protection  
P.O. Box CN029  
Trenton, NJ 08625

Mr. John O'Dowd, Acting Chief  
Bureau of Flood Plain Regulation  
Division of Water Resources  
N.J. Dept. of Environmental Protection  
P.O. Box CN029  
Trenton, NJ 08625

CLINTON RESERVOIR DAM (NJ00314)

CORPS OF ENGINEERS ASSESSMENT OF GENERAL CONDITIONS

This dam was inspected on 14 November, 4 and 15 December 1979 by Harris - ECI Associates, Inc., under contract to the State of New Jersey. The State, under agreement with the U.S. Army Engineer District, Philadelphia, had this inspection performed in accordance with the National Dam Inspection Act, Public Law 92-367.

Clinton Reservoir Dam, a high hazard potential structure, is judged to be in good overall condition. The dam's spillway is considered inadequate because a flow equivalent to 58 percent of the Probable Maximum Flood would cause the dam to be overtopped. To ensure adequacy of the structure, the following actions, as a minimum, are recommended:

a. The spillway's adequacy should be determined by a qualified professional consultant engaged by the owner using more sophisticated methods, procedures, and studies within six months from the date of approval of this report. Within three months of the consultant's findings, remedial measures to ensure spillway adequacy should be initiated.

b. The owner should develop an emergency action plan (if one is not already available) outlining actions to be taken by the operator to minimize downstream effects of an emergency and establish a flood warning system for the downstream communities within three months from the date of approval of this report.

c. The following remedial actions should be initiated within twelve months from the date of approval of this report:

(1) Observation wells or piezometers should be installed in the embankment and the spillway discharge channel to determine the location of the phreatic surface and the paths of the seepage observed.

(2) The flow of seepage should be monitored monthly to determine its volume and whether it presents a problem to the safety of the dam.

(3) All trees and brush should be removed from the side slopes to avoid problems which may develop from roots. The embankment face should then be reseeded to develop a growth of grass for surface erosion protection.

(4) Remove vegetation from the downstream channel.


d. Within one year from the date of approval of this report, repair the crack across the spillway; replace the missing boulders in the right abutment masonry wall and regrout the wall.



e. Within two years from the date of approval of this report, consider providing additional low-level outlet facilities to decrease the draw down time.

f. Within one year from the date of approval of this report, the owner should develop written operating procedures and a periodic maintenance plan to ensure the safety of the dam.

APPROVED:

  
JAMES G. TON  
Colonel, Corps of Engineers  
District Engineer

DATE: 9 JULY 1980

PASSAIC RIVER BASIN  
CLINTON BROOK, PASSAIC COUNTY  
NEW JERSEY

CLINTON RESERVOIR DAM  
NJ00314

PHASE I INSPECTION REPORT  
NATIONAL DAM SAFETY PROGRAM

DEPARTMENT OF THE ARMY  
PHILADELPHIA DISTRICT, CORPS OF ENGINEERS  
PHILADELPHIA, PENNSYLVANIA 19106

APRIL 1980

PHASE I INSPECTION REPORT  
NATIONAL DAM SAFETY PROGRAM

Name: Clinton Reservoir Dam, I.D. NJ 00314  
State Located: New Jersey  
County Located: Passaic County  
Stream: Clinton Brook  
River Basin: Passaic River  
Date of Inspection: November 14, December 4 and 15, 1979

Assessment of General Conditions

Clinton Reservoir Dam is an earthfill dam containing a broad crested concrete weir spillway at the left end of the dam. The overall condition of the dam is good. There is no major sign of distress or instability in the embankment. There are boulders missing from the right abutment masonry wall and the abutment wall also needs to be regouted. The downstream channel is well defined. The operation of the low-level outlet was demonstrated satisfactorily. The hazard potential is rated as "high".

The adequacy of Clinton Reservoir Dam is considered questionable in view of its lack of spillway capacity to pass the SDF (PMF) without overtopping the dam. The spillway is capable of passing a flood equal to 57 percent of the PMF, and is assessed as "inadequate".


At present, the engineering data available is not sufficient to make a definitive statement on the stability of the dam, but based on the findings of the visual inspection, the preliminary assessment of static stability is that it is satisfactory. The following actions are recommended along with a timetable for their completion. All recommended actions should be conducted under the supervision of an Engineer who is experienced in the design, construction and inspection of dams.

1. Carry out a more precise hydrologic and hydraulic analysis of the dam within twelve months, to determine the need and type of mitigating measures necessary. Based on the results of these studies remedial measures should be instituted. This should include the installation of a tailwater gage.
2. Observation wells or piezometers should be installed in the embankment and spillway discharge channel to determine the location of the phreatic surface and the paths of the seepage observed. This should be done within twelve months.

3. The flow of seepage should be monitored monthly to determine its volume and whether it presents a problem to the safety of the dam.
4. Repair the crack across the spillway; replace the missing boulders in the right abutment wall and regrout the wall. This work should be completed within twelve months.
5. All brush and trees should be removed from the downstream and upstream slopes to avoid problems which may develop from roots. The embankment face should then be seeded to develop a growth of grass for surface erosion protection. This program should be started within twelve months.
6. Remove vegetation from downstream channel within twelve months.
7. The owner should develop an emergency action plan (if one is not already available) outlining actions to be taken by the operator to minimize downstream effects of an emergency and establish a flood warning system for the downstream communities within three months.

Furthermore, while of a less urgent nature, the following additional action is recommended and should be carried out within twenty-four months.

1. Consider providing additional low-level outlet facilities to decrease drawdown time.
2. Conduct a complete topographic survey of the dam and surrounding area, in order to develop a detailed plan and several cross-section of the dam. Annotate and update the existing drawings, and form a coherent as-built set.
3. The owner should develop, within one (1) year after formal approval of the report, written operating procedures and a periodic maintenance plan to insure the safety of the dam.



John P. Talerico, P.E.  
HARRIS-ECI ASSOCIATES



Photo taken on February 15, 1980

# CLINTON RESERVOIR DAM

View, from spillway, toward right end of dam. Valve house is visible at left center. Gate riprap on both the downstream, bottom left, and the upstream, bottom

## PREFACE

This report is prepared under guidance contained in the Recommended Guidelines for Safety Inspection of Dams, for Phase I Investigations. Copies of these guidelines may be obtained from the office of the Chief of Engineers, Washington, D.C. 20314. The purpose of a Phase I Investigation is to identify expeditiously those dams which may pose hazards to human life or property. The assessment of the general condition of the dam is based upon available data and visual inspections. Detailed investigation, and analyses involving topographic mapping, subsurface investigations, testing, and detailed computational evaluations are beyond the scope of a Phase I investigation; however, the investigation intended to identify any need for such studies.

In reviewing this report, it should be realized that the reported condition of the dam is based on observations of field conditions at the time of inspection along with data available to the inspection team. It is important to note that the condition of a dam depends on numerous and constantly changing internal and external conditions, and is evolutionary in nature. It would be incorrect to assume that the present condition of the dam will continue to represent the condition of the dam at some point in the future. Only through continued care and inspection can there be any chance that unsafe conditions be detected.

Phase I inspections are not intended to provide detailed hydrologic and hydraulic analyses. In accordance with the established Guidelines, the Spillway Test flood is based on the estimated "Probable Maximum Flood" for the region (greatest reasonably possible storm runoff), or fractions thereof. The test flood provides a measure of relative spillway capacity and serves as an aide in determining the need for more detailed hydrologic and hydraulic studies, considering the size of the dam, its general condition and the downstream damage potential.

## TABLE OF CONTENTS

### ASSESSMENT OF GENERAL CONDITIONS

#### OVERVIEW PHOTO

#### PREFACE

	<u>Page</u>
SECTION 1 PROJECT INFORMATION .....	1
1.1 General .....	1
1.2 Description of Project .....	2
1.3 Pertinent Data .....	4
SECTION 2 ENGINEERING DATA.....	6
2.1 Design .....	6
2.2 Construction.....	6
2.3 Operation .....	6
2.4 Evaluation.....	6
SECTION 3 VISUAL INSPECTION.....	8
3.1 Findings .....	8
SECTION 4 OPERATION PROCEDURES.....	10
4.1 Procedures .....	10
4.2 Maintenance of Dam.....	10
4.3 Maintenance of Operating Facilities.....	10
4.4 Evaluation .....	10
SECTION 5 HYDRAULIC/HYDROLOGIC .....	11
5.1 Evaluation of Features.....	11
SECTION 6 STRUCTURAL STABILITY .....	13
6.1 Evaluation of Structural Stability.....	13
SECTION 7 ASSESSMENT/REMEDIAL MEASURES .....	15
7.1 Dam Assessment .....	15
7.2 Remedial Measures .....	15

TABLE OF CONTENTS CONTINUED

<u>PLATES</u>	<u>No.</u>
KEY MAP & VICINITY MAP.....	1 & 1A
GEOLOGIC MAP.....	2
DRAWINGS OF DAM.....	3 - 5

<u>APPENDICES</u>	
APPENDIX A - CHECK LIST - VISUAL OBSERVATIONS CHECK LIST - ENGINEERING, CONSTRUCTION, MAINTENANCE DATA	1- 14
APPENDIX B - PHOTOGRAPHS	
APPENDIX C - SUMMARY OF ENGINEERING DATA	1
APPENDIX D - HYDROLOGIC COMPUTATIONS	1 - 5



PHASE I INSPECTION REPORT  
NATIONAL DAM SAFETY PROGRAM  
CLINTON RESERVOIR DAM, I.D. NJ 00314

SECTION 1

1. PROJECT INFORMATION

1.1 General

a. Authority

The National Dam Inspection Act (Public Law 92-367, 1972) provides for the National Inventory and Inspection Program by the U.S. Army Corps of Engineers. This inspection was made in accordance with this authority under Contract C-FPM No. 35 with the State of New Jersey who, in turn, is contracted to the Philadelphia District of the Corps of Engineers, and was carried out by the engineering firm of Harris-ECI Associates, Woodbridge, New Jersey.

b. Purpose of Inspection

The visual inspection of Clinton Reservoir Dam was made on November 14, 1979. The purpose of the inspection was to make a general assessment as to the structural integrity and operational adequacy of the dam embankment and its appurtenant structures.

c. Scope of Report

The report summarizes available pertinent data relating to the project; presents a summary of visual observation made during the field inspection; presents an evaluation of hydrologic and hydraulic conditions at the site; presents an evaluation as to the structural adequacy of the various project features; and assesses the general condition of the dam with respect to safety.

## 1.2 Description of Project

### a. Description of Dam and Appurtenances

Clinton Reservoir Dam is an earthfill dam about 1,530 feet long and 55 feet high with a concrete core wall. There is a 300-foot wide broad crested concrete weir spillway at the dam's left end. The crest of the spillway is 5.5 feet below the top of the dam. The embankment crest has a width of 18 feet with its upstream and downstream slopes being 2H:1V. A 16-foot wide berm upstream and a 12-foot wide berm downstream intercept the slopes 6 feet from the embankment crest. Riprap protection has been placed on the embankment's entire upstream slope and on the downstream slope from the berm to its toe.

The low-level outlet consists of an arch-shaped tunnel under the embankment. The tunnel is cut through rock and it is located about 140 feet from the dam's right end. The flow through the tunnel is controlled by four cone valves having 8, 10, 12 and 14 inch diameters. Four 42-inch diameter cast iron pipes are at both the upstream side and the downstream side of the valves. These pipes are connected to the four cone valves by the use of reducers and increasers. Stems from the valves extend up into a brick Valve House where two of the valves are operated by handwheels and the remaining two are operated by cranks. According to Plate 4, the upstream side of the tunnel is screened. The tunnel outlet exits at the embankment's toe of slope. From this point the flow passes into a channel cut out of rock. This flow joins with the spillway's flow about 1,000 feet from the spillway. The flow, known as Clinton Brook, passes under Clinton Road about 1,300 feet from the spillway.

### b. Location

Clinton Reservoir Dam is located on Clinton Brook in the Township of West Milford, Passaic County, New Jersey. It is accessible by way of Clinton Road.

### c. Size Classification

According to the "Recommended Guidelines for Safety Inspection of Dams" by the U.S. Department of the Army, Office of the Chief Engineers, the dam is classified in the dam size category as being "intermediate", since its storage volume of 14,272 acre-feet is more than 1,000 acre-feet, but less than 50,000 acre-feet. The dam is also classified as "intermediate" because its height of 55.5 feet is greater than 40 feet but less than 100 feet. The overall size classification of Clinton Reservoir Dam is classified as "intermediate" in size.

d. Hazard Classification

A hazard potential classification of "high" has been assigned to the dam on the basis that a hypothetical failure would result in excessive damage to Clinton Road immediately downstream of the dam. There are also three houses, LaRue Road and N.J. Route 23 further downstream of the dam. Because these three roads are heavily traveled and because the three houses are occupied, the possibility exists of the loss of more than a few lives in the event of dam failure.

e. Ownership

Clinton Reservoir Dam is owned by:

City of Newark  
Department of Public Works  
Division of Water Supply  
1294 McBride Avenue  
Little Falls, N.J. 07424

Attention: Mr. Daniel Berardinelli  
(201) 265-4965

f. Purpose

Clinton Reservoir Dam is presently used as a storage reservoir for the water supply system.

g. Design and Construction History

Clinton Reservoir Dam was constructed in the early 1890's. Plans showing the original design are available but no design criteria or construction report could be found.

h. Normal Operating Procedures

Clinton Reservoir is a primary storage reservoir for the City of Newark Water Supply System. It is one of the five storage reservoirs that is drawdown in sequence in order to permit filling of all the reservoirs in a uniform manner during rainfall.

1.3 Pertinent Data

a. Drainage Area 9.10 sq. mi.

b. Discharge at Dam Site

Ungated spillway capacity at  
elevation of top of dam: 10,448 cfs (997.50 NGVD)

Total spillway capacity at  
maximum pool elevation (SDF): 23,352 cfs (999.26 NGVD)

c. Elevation (Feet above NGVD)

Top of dam: 997.50  
Maximum pool design surcharge (SDF): 999.72  
Recreation pool: N/A  
Spillway crest: 992.00  
Streambed at centerline of dam: 942.0 (estimated)  
Maximum tailwater: 951.5 (estimated)

d. Reservoir

Length of maximum pool: 9,500 ft. (estimated)  
Length of normal pool: 9,000 ft. (estimated)

e. Storage (acre-feet)

Spillway crest: 10,796  
Top of dam: 13,372  
Maximum pool (SDF): 14,272

f. Reservoir Surface (acres)

Top of dam: 507 (estimated)  
Maximum pool (SDF): 546 (estimated)  
Spillway crest: 405 (992 NGVD)

g. Dam

Type:	Earthfill with concrete core
Length:	1,530.0 ft. (effective)
Height:	55.5 ft.
Top width:	18 ft.
Side slopes - Upstream:	2H:1V
- Downstream:	2H:1V
Zoning:	Unknown
Impervious core:	Concrete - 5.0 to 5.4 ft. wide
Cutoff:	None
Grout curtain:	Unknown

h. Diversion and Regulating Tunnel

N/A

i. Spillway

Type:	Broad crest weir
Length of weir:	300 ft.
Crest elevation:	992.0 NGVD
Gates:	None
U/S Channel:	Clinton Reservoir
D/S Channel:	The channel from the spillway meets the channel from the tunnel under the Value House approximately 1,000 feet from spillway.

j. Regulating Outlets

Low level outlet:	4 - 42 inch cast iron pipes with 8,10,12, and 14 inch cone valves.
Controls:	4 manually operated cone valves
Emergency gate:	Same as above.
Outlet:	950 NGVD

## SECTION 2

### 2. ENGINEERING DATA

#### 2.1 Design

Drawings for the original construction of Clinton Reservoir Dam in the early 1890's and the modifications in 1960, are available from the City of Newark, Division of Water Supply, offices on McBride Avenue in Little Falls, N.J. One of these drawings shows that the concrete core wall is founded on rock; and it also shows the rock profile. No data from soil borings, soil tests, or other geotechnical data is available. Data concerning the hydraulic capacity of the spillway is also unavailable.

#### 2.2 Construction

Data is not available concerning the as-built construction of the dam. No data exists of the construction methods, borrow sources, or other data pertinent to the construction of the dam.

#### 2.3 Operation

Daily records have been kept since 1972 of the water level in the reservoir. The water level indicator was inspected and found in satisfactory condition.

According to the City of Newark's Division of Water Supply, five storage reservoirs, of which Clinton Reservoir is a primary one, are utilized for their supply system. Basically, the five reservoirs are utilized in sequence in order to permit filling of all reservoirs uniformly during rainfall. Looking downstream, from North to South, Clinton Reservoir is located number 2 in the five-reservoir system.

#### 2.4 Evaluation

##### a. Availability

The availability of engineering data is fair. The drawings and verbal information concerning the original construction and the subsequent modifications can be obtained from the Manager's Office, Division of Water Supply, listed above under Section 2.1.

##### b. Adequacy

The engineering data available, together with that obtained in the field, were adequate to perform hydrologic and hydraulic computations. The data was insufficient to perform a stability analysis, but preliminary evaluation could be made based on visual observations.

c. Validity

Information contained in the drawings and checked by limited field measurements appears to be valid. However, field investigation revealed no riprap on the embankment's downstream side slope from the top of the embankment to the berm. See Plate 4.

## SECTION 3

### 3. VISUAL INSPECTION

#### 3.1 Findings

##### a. General

The visual inspection of Clinton Reservoir Dam revealed the dam and spillway to be in good condition, but in need of minor repairs. The lake level was below the spillway's crest at the time of the inspection.

##### b. Dam

The earth embankment appears sound. No surface cracking on the embankment or at the toe was noted. No sloughing or erosion of the embankment and abutment slopes were visible. No misalignment of the embankment in the horizontal or vertical plane was evident. No rip-rap failures were noted. Minor seepage, running clear, was noticed at the downstream toe of the embankment. The seepage is located at a point that is about 400 feet from the Valve House, toward the spillway, and the location appears to be at the "Bed of Old Brook" shown on Plate 3. The embankment is clear of vegetation but there are a few trees growing on its side slopes. No evidence of burrowing by animals was observed.

##### c. Appurtenant Structures

#### 1. Spillways

The broad crest weir spillway was in fair condition. The vertical and horizontal alignment of the crest was good. A transverse crack exists across the spillway. There is vegetation growing on the downstream side of the spillway. Boulders were missing from the right abutment masonry wall and the abutment wall also needed re-grouting. Leakage was noticed in the downstream channel of the spillway. The channel is riprapped.

#### 2. Outlet Works

There are four 42-inch diameter cast iron pipes underneath the Valve House. The pipes, in good condition, discharge their flow into a tunnel cut through rock underneath the embankment. The tunnel is arch-shaped, about 12 feet high and about 24 feet wide at its base, and in good condition.



#### d. Reservoir Area

The reservoir has moderate to steep side slopes. There is no indication of slope instability.

#### e. Downstream Channel

Two downstream channels exist - one from the spillway and the other from the tunnel underneath the embankment. These channels meet approximately 1,000 feet from the spillway. Both channels are in good condition.

The channel receiving the flow from the tunnel is cut through rock and leakage was noticed on both banks of the channel near the tunnel. The tunnel is in good condition.

Approximately 300 feet downstream from where the two channels meet, or about 1,300 feet from the spillway, the channel crosses under Clinton Road. One house, located approximately one mile from the spillway, is situated on the channel's left bank near LaRue Road. Two houses, located about 7,000 feet from the spillway at LaRue Road, are situated on the channel's right bank. The channel crosses under N.J. Route 23 about 2 miles from the spillway.

#### f. Geology

A visual inspection of geologic features shows shale exposed at both embankment ends. The shale is gray in color, with evidence of slaty cleavage that fractures when exposed into pencil-shaped pieces. It also appears to contain traces of coarser material. The presence of this material does not appear to change its structure enough to vary its permeability or alter its integrity.

At the toe of the slope of the broad crested weir, a massive rock was noted. Access to it was difficult but its most noteworthy feature was the presence of secondary quartz filling the joints. The rock appears sound though with only little physical or chemical weathering.

The bedding generally strikes N 55 E and dips  $65^{\circ}$  -  $70^{\circ}$  throughout the site. There are two, or possibly three joint sets in evidence. One set, striking N 55 E and varying  $30^{\circ}$  -  $38^{\circ}$  N in dip appears both in the low-level outlet tunnel beneath the embankment and the left dam end. Another set, which may be two distinct sets, had the following attitudes of lineation.

Tunnel N  $35^{\circ}$  W  $\sim$  V

Left N  $55^{\circ}$  W  $60^{\circ}$  S  
end of  
dam

## SECTION 4

### 4. OPERATIONAL PROCEDURES

#### 4.1 Procedures

Clinton Reservoir Dam is a primary storage reservoir for the City of Newark's water supply system. According to their Division of Water Supply, Clinton Reservoir Dam is one of five storage reservoirs. Basically, the five reservoirs are utilized in sequence in order to permit filling of all reservoirs uniformly during rainfall.

#### 4.2 Maintenance of the Dam

Persently, there is no regular inspection and maintenance program for the dam and appurtenant structures. Spot maintenance is performed on the valve, or gate, house and appurtenant structures but there is no routine maintenance for riprap stability, reservoir and stream cleaning.

#### 4.3 Maintenance of Operating Facilities

The low-level outlet operating facilities consist of four manually operated cone valves and one water level indicator. At the time of inspection all four valves and the water level indicator were satisfactorily demonstrated. A flap gate is attached to each of the four pipes, at the upstream end of the pipe, opposite the cone valves. According to the owner, the flap gates operate satisfactorily and that a gate is closed when the valve online needs repairing.

#### 4.4 Evaluation

The present operation and maintenance procedures are good with the dam and spillway being maintained in a serviceable condition.

## SECTION 5

### 5. HYDRAULIC/HYDROLOGIC

#### 5.1 Evaluation of Features

##### a. Design

The drainage area above Clinton Reservoir Dam is approximately 9.10 square miles. A drainage map of the watershed of the dam site is presented on Plate 1, Appendix D.

The topography within the basin is flat to moderately sloped. Elevations range from approximately 1,420 feet above NGVD at the north part of the watershed to about 998 feet at the dam site. Land use patterns within the watershed are mostly woodland.

The evaluation of the hydraulic and hydrologic features of Clinton Reservoir was based on criteria set forth in the Corps' guidelines and additional guidance provided by the Philadelphia District, Corps of Engineers. The SDF for the dam is the PMF.

The probable maximum flood (PMF) was calculated from the probable maximum precipitation using Hydrometeorological Report No. 33 with standard reduction factors. Due to the small drainage area, the SCS triangular hydrograph transformed to a curvilinear hydrograph was adopted for developing the unit hydrograph, with the aid of the HEC-1DB Flood Hydrograph Computer Program.

Initial and infiltration loss rates, were applied to the Probable Maximum Precipitation to obtain rainfall excesses. The rainfall excesses were applied to the unit hydrograph to obtain the PMF and various ratios of the PMF utilizing program HEC-1DB.

The SDF peak outflow calculated for the dam is 23,352 cfs. This value is derived from the PMF, and results in overtopping of the dam, assuming that the reservoir was originally at the spillway crest elevation.

The stage outflow relation for the spillway was determined from the geometry of the spillway and dam, utilizing HEC-1DB program.

The reservoir stage-storage capacity relationship to the spillway level was obtained from the City of Newark, Division of Water Supply. The reservoir stage-storage capacity relationship beyond the spillway level was computed directly by the conic method, utilizing the HEC-IDB program. The reservoir surface area at the elevations beyond the spillway level was measured by planimeter from a U.S.G.S. Quadrangle topographic map. Reservoir storage capacity included surcharge levels exceeding the top of the dam, and the spillway rating curve was based on the assumption that the dam remains intact during routing.

Drawdown calculations indicate that to empty the reservoir to an elevation of 950.0 NGVD through the four low-level cone valves would take 37 days, assuming a 2 c.f.s./square mile inflow. This is considered to be an excessive drawdown period and provision of additional outlets should be considered.

b. Experience Data

Records of the daily reservoir stage level have been maintained since 1972. The reservoir water level is usually at 992 NGVD. There have only been a few occasions of the reservoir level being recorded higher than 992 NGVD and none of the water level exceeding 997.5 NGVD.

c. Visual Observation

Two downstream channels exist - one from the spillway and the other from the tunnel underneath the embankment. These channels meet approximately 1,000 feet from the spillway. Both channels are in good condition.

The channel receiving the flow from the tunnel is cut through rock and leakage was noticed on both banks of the rock channel near the tunnel.

Approximately 300 feet downstream from where the two channels meet, or about 1,300 feet from the spillway, the channel crosses under Clinton Road.

The slopes of the reservoir are moderate to steep and do not exhibit signs of instability. The drainage area is wooded and moderately flat sloped.

d. Overtopping Potential

A storm of magnitude equivalent to the SDF would cause overtopping of the dam to a height of 1.76 feet. Computations indicate that the dam can pass approximately 57 percent of the PMF without overtopping the dam crest. Since the PMF is the Spillway Design Flood (SDF) for this dam, according to the "Recommended Guidelines for Safety of Dams" by the Corps of Engineers, the spillway capacity of the dam is assessed as "inadequate".

## SECTION 6

### 6. STRUCTURAL STABILITY

#### 6.1 Evaluation of Structural Stability

##### a. Visual Observations

There are no major signs of distress in the embankment of the Clinton Reservoir Dam. Trees growing on the embankment sides could pose a threat to stability. Seepage was observed at three locations. One location is about 400 feet left of the Valve House, the second location was in the spillway discharge channel, and the third location was in the banks of the channel from the outlet tunnel. The seepage has not been monitored and no information was uncovered concerning their duration or flow rates. No evidence of burrowing animals was observed. The spillway is in good condition but the right abutment masonry wall needs repairs.

##### b. Design and Construction Data

No design computations relating to stability were uncovered during the report preparation phase. No embankment or foundation soil parameters are available for carrying out a conventional stability analysis on the embankment. No construction data or specifications relating to the degree of embankment compaction are available for use in the stability analysis.

##### c. Operating Records

No operating records are available relating to the stability of the dam. The dam and spillway have served satisfactorily since its construction in the early 1890's.

##### d. Post-Construction Changes

The Valve House was built in 1960.

##### e. Static Stability

A static stability analysis was not performed for Clinton Reservoir Dam because the lack of data on which to base assumptions of material properties within embankment zones might produce misleading results, but based on the findings of the visual inspection, the preliminary assessment of static stability is that it is satisfactory.

f. Seismic Stability

The dam is located in Seismic Zone 1, as defined in Recommended Guidelines for Safety Inspection of Dams, prepared by the Corps of Engineers. In general, projects located in Seismic Zones 0, 1 and 2 may be assumed to present no hazard from earthquake, provided the static stability conditions are satisfactory and conventional safety margins exist, and based on the findings of the visual inspection, the preliminary assessment of the static and seismic stabilities is that they are satisfactory.

## SECTION 7

### 7. ASSESSMENT/REMEDIAL MEASURES

#### 7.1 Dam Assessment

##### a. Safety

The dam has been inspected visually and a review has been made of the available engineering data. This assessment is subject to the limitations inherent in the visual inspection procedures stipulated by the Corps of Engineers for a Phase I report.

The safety of Clinton Reservoir Dam is in question because the dam does not have adequate spillway capacity to pass the SDF which is the PMF without overtopping. Overtopping of the dam carries with it the danger of possible progressive failure of the dam. The dam's present spillway capacity is about 57 percent of the PMF.

No definitive statement pertaining to the safety of the embankment can be made without acquisition of embankment material engineering properties, but based on the findings at the visual inspection, the preliminary assessment of static stability is that it is satisfactory.

##### b. Adequacy of Information

The information uncovered was adequate to perform hydrologic and hydraulic computations. The data was insufficient to perform even an approximate computation of the dam's stability. A preliminary assessment of the dam could be made by visual observation only.

##### c. Urgency

The remedial measures and recommended actions along with a timetable for their completion are detailed below. All recommended action should be conducted under the supervision of an engineer who is experienced in the design, construction and inspection of dams.

#### 7.2 Remedial Measures

##### a. Alternatives for Increasing Spillway Capacity

Alternatives for increasing spillway capacity are as follows:

1. Increase the embankment height, thus permitting a higher discharge to pass over the spillway and reducing the possibility of overtopping.

2. Lower the spillway crest elevation.
3. Increase the effective spillway crest length.
4. A combination of any of the above alternatives.

b. Recommendations

1. Carry out a more precise hydrologic and hydraulic analysis of the dam within twelve months, to determine the need and type of mitigating measures necessary. If required, conduct a study of the means of increasing spillway discharge capacity and develop alternative schemes for construction. This should include the installation of headwater and tailwater gages. The ability of the dam to withstand overtopping should also be studied.
2. Observation wells or piezometers should be installed in the embankment and the spillway discharge channel to determine the location of the phreatic surface and the paths of the seepage observed. This should be done within twelve months.
3. The flow of seepage should be monitored monthly to determine its volume and whether it presents a problem to the safety of the dam.
4. Repair the crack across the spillway, replace the missing boulders in the right abutment masonry wall and regrout the wall. This work should be completed within twelve months.
5. All trees and brush should be removed from the side slopes to avoid problems which may develop from roots. The embankment face should then be reseeded to develop a growth of grass for surface erosion protection. This program should be started within twelve months.
6. Remove vegetation from the downstream channel within twelve months.

The following additional actions are recommended:

1. The owner should develop an emergency action plan (if one is not already available) outlining actions to be taken by the operator to minimize downstream effects of an emergency and establish a flood warning system for the downstream communities within three months.




2. Consider providing additional low-level outlet facilities to decrease the drawdown time.


c. O & M Procedures

The owner should develop, within one (1) year after formal approval of the report, written, operating procedures and a periodic maintenance plan to insure the safety of the dam.


P L A T E S

**CLINTON RESERVOIR DAM**  
**WEST MILFORD TWP.**  
**PASSAIC COUNTY, N. J.**





Scale in Feet (Approx.)  
 2,000 0 2,000 4,000 6,000 8,000 10,000



### LEGEND:


#### DEVONIAN

- Db Bellvale Sandstone
- Dsk Skunnemuck Conglomerate

#### PRECAMBRIAN

- am Amphibolite
- gh Mostly Hornblende Granite and Gneiss
- qob Quartz-Oligoclase-Biotite Gneiss
- gpx Pyroxene Gneiss


## GEOLOGIC MAP CLINTON RESERVOIR DAM




2

TOP OF MAIN E 3110

TIE OF CONCRETE CORE 1 3111  
LEVEL OF OVERLAY 1 3110




PROFILE SHOWING FOUNDATION OF



3



PROFILE SHOWING FOUNDATION OF CONCRETE CORE &c.







4



8c.








SECTION - OVERFLOW ON  
A.B.

SCALE 10 FT. = 1 IN.

EAST JERSEY  
PLAN PROJ

CLIN

PLAN 30 FT. = 1 IN. H. 100



THE  
EAST JERSEY WATER COMPANY  
PLAN PROFILE & SECTION  
OF  
CLINTON DAM


SECTION D

JUNE 1892

SCALES

PLAN 50 FT. TO 1 IN. SECTION 50 FT. TO 1 IN. VERTICAL 100 FT. TO 1 IN. SECTION 15 FT. TO 1 IN.

CASE 2 POCKET 3 FOLDER 2 FILE



SECTION - DAM

RECEIVED

NOV 14 1979


HARRIS, WMA  
WOODBRIDGE, IL 6

PLATE 3

CLINTON RESERVOIR


NOTE

SLUICE GATE AND VAULT IS NOT




2

GATES AND VAULTS NOT IN THIS CONTRACT




3





8



ELEVATION OF GATE HOUSE AND PARTIAL SECTION OF VALVES AND VALVE CHAMBERS  
LOOKING SOUTH

CLINTON  
RESERVOIR


INLET TUNNEL

95' 8"

A

2

SECTION A-A THREE



PLAN OF SLUICE GATE VAULTS, VALVE CHAMBERS AND TUNNEL

95°6'

DISCHARGE TUNNEL

A.

MAP OF WORK SITE  
SCALE 1 INCH = 1 MILE

CLINTON RESERVOIR

WEIR DAM

RAILWAY

VALVE CHAMBERS

VAN ORDER ROAD

DEPT  
DIVISION

CONTRACTS NO 145 146A

INSTALLATION

CLI

APPROVALS


RECEIVED

NOV 14 1979

HARRIS, INC.  
WOODBRIDGE, N. J.

*[Handwritten signatures and initials]*  
bismundres

MAP OF WORK SITE  
SCALE 1 INCH = 1 MILE



DEPARTMENT OF PUBLIC WORKS  
DIVISION OF WATER SUPPLY  
NEWARK, N.J.

CONTRACTS NO 146-146A

JOB NO 4025

INSTALLATION OF 8, 10, 12 & 14" CONE VALVES  
AND VALVE HOUSE

CLINTON RESERVOIR

RECEIVED

NOV 14 1979

HARRIS, INC.  
WOODBRIDGE, N.J.

APPROVALS

*William*  
ALLISON ENGINEER

*Edward*  
BYRNE ENGINEER

*biwandres*

SCALE OF 1/2 INCH = 100 FEET  
DRAWN BY: M. J. M.  
CHECKED BY:


REVISED

DATE: 11/14/79  
BY: M. J. M.  
APPROVED BY: M. J. M.


DATE

PLATE 5


COPY 2 FOR 6.5 INCH 1/2 SCALE 1/2 INCH = 100 FEET




UP STREAM ELEVATION—UNCOVERED




SE





SECTION ON LINE AB



EAST JERSEY WATER COM

# CLINTON GATE


MARCH 1892

PLATFORM BEAMS

See p. 4

See p. 5

See p. 6





AST JERSEY WATER COMPANY


# NTON GATE HOUSE

MARCH 1892

PLATFORM BEAMS


Scale 1" = 10'

Long drawn



PLAN-UNCOVERED  
Size 8 - 4

FLAP GATES AND HOISTING GEAR  
Size 8 - 4




PLAN - UNCOVERED

Scale 1/4" = 1'


FLAP GATES AND HOISTING GEAR

Scale 1/4" = 1'




# STAIRS AND LANDING

Scale 1/4" = 1'-0"




# CONTRACTING PIPES

Scale 1/4" = 1'-0"




544 1. 4



PIPES

UP-STREAM ARCH... SCREEN  
Sent, 4



CASE 2 POCKET 3 FOLDER 2 FILE 35 ACC 499

RECEIVED

**NOV 14 1950**

**HARRIS, INC.**

# PLATE 4

APPENDIX A

CHECK LIST - VISUAL OBSERVATIONS

CHECK LIST - ENGINEERING, CONSTRUCTION  
MAINTENANCE DATA

CHECK LIST  
VISUAL INSPECTION  
PHASE 1

Name Dam CLINTON RESERVOIR DAM County Passaic State New Jersey Coordinators NJ-DEP

Date(s) Inspection November 14, 1979 Weather Cloudy Temperature 48° F

December 4, 1979  
December 15, 1979

Pool Elevation at Time of Inspection 990 NGVD Tailwater at Time of Inspection 945.5 NGVD

Inspection Personnel:

November 14, 1979

Chuck Chin  
Eugene Koo (Recorder)  
Thomas Lakovich

December 4, 1979

Chuck Chin  
James McCormick

December 15, 1979

Walter Jones

OWNER/REPRESENTATIVE:

December 4, 1979

Glen Norman, Maintenance Foreman  
City of Newark  
Department of Public Works  
Division of Water Supply  
1294 McBride Avenue  
Little Falls, N.J. 07424

# CONCRETE/MASONRY DAMS

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS AND RECOMMENDATIONS
SEEPAGE OR LEAKAGE N/A		
STRUCTURE TO ABUTMENT/EMBANKMENT JUNCTIONS N/A		
DRAINS N/A		
WATER PASSAGES N/A		
FOUNDATIONS N/A		



# CONCRETE/MASONRY DAMS

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS AND RECOMMENDATIONS
SURFACE CRACKS CONCRETE SURFACES N/A		
STRUCTURAL CRACKING N/A		
VERTICAL & HORIZONTAL ALIGNMENT N/A		
MONOLITH JOINTS N/A		
CONSTRUCTION JOINTS N/A		

# EMBANKMENT

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS AND RECOMMENDATIONS
SURFACE CRACKS None noticed.		
UNUSUAL MOVEMENT OR CRACKING AT OR BEYOND THE TOE None observed.		
SLOUGHING OR EROSION OF EMBANKMENT AND ABUTMENT SLOPES None visible.		
VERTICAL & HORIZONTAL ALIGNMENT OF THE CREST Good.		
RIPRAP FAILURES None		

# EMBANKMENT

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS AND RECOMMENDATIONS
EARTH EMBANKMENT: Good condition.	Has a few evergreen trees growing on its side slopes	Remove trees.
JUNCTION OF EMBANKMENT AND ABUTMENT, SPILLWAY AND DAM Good.		
ANY NOTICEABLE SEEPAGE Minor seepage, running clear, was noticed at the downstream toe of the embankment. The seepage is located at a point that is about 400 feet from the Valve House, toward the spillway. The seepage appears to be located at the "Bed of Old Brook" shown on Plate 3.		Monitor seepage for clearness and quantity.
STAFF GAGE AND RECORDER None		
DRAINS None.		

# OUTLET WORKS

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS AND RECOMMENDATIONS
CRACKING & SPALLING OF CONCRETE SURFACES IN STILLING BASIN	Stilling basin is "tunneled" rock in good condition.	
INTAKE STRUCTURE	Underwater, not visible.	
OUTLET STRUCTURE	Four (4) 42-inch cast iron pipes, in good condition, underneath the Valve House discharge into a tunnel under the embankment.	
OUTLET FACILITIES	The tunnel under the embankment, receiving the discharge from the four pipes mentioned above, is cut through rock. The tunnel is arch-shaped. It is about 12 feet high and about 24 feet wide at its base. The flow through the pipes is controlled by cone valves.	
EMERGENCY GATE	None	

# UNGATED SPILLWAY

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS AND RECOMMENDATIONS
CONCRETE WEIR Fair condition. A transverse crack exists across the concrete spillway. Vegetation is growing on downstream side of spillway.		Repair crack and remove vegetation.
APPROACH CHANNEL Reservoir. Boulders missing in right abutment masonry wall. Also, the abutment wall needs re-grouting.		Repair walls.
DISCHARGE CHANNEL Riprap, in good condition, at bottom of channel. Downstream side of spillway has leakage. Leakage is located about 60 feet downstream from the spillway crest, about 5 feet from the right abutment wall.		Monitor leakage for clearness and quantity.
BRIDGE AND PIERS None		

# GATED SPILLWAY

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS AND RECOMMENDATIONS
CONCRETE SILL N/A		
APPROACH CHANNEL N/A		
DISCHARGE CHANNEL N/A		
BRIDGE AND PIERS N/A		
GATES & OPERATION EQUIPMENT N/A		

# INSTRUMENTATION

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS AND RECOMMENDATIONS
MONUMENTATION/SURVEYS None		
OBSERVATION WELLS None		
WEIRS None		
PIEZOMETERS None		
OTHER	Water level indicator. The type of level indicator was Weighted Steel Tape and Float. Operation of the level indicator was checked and found satisfactory.	

# RESERVOIR

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS AND RECOMMENDATIONS
SLOPES	Moderate to steep side slopes. No indication of slope instability.	
SEDIMENTATION	None noticed.	



# DOWNSTREAM CHANNEL

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS AND RECOMMENDATIONS
CONDITION (OBSTRUCTIONS, DEBRIS, ETC.)	Spillway channel is in good condition. The channel receiving flow from tunnel under embankment, at Valve House, is also in good condition. This channel is cut through rock and leakage was noticed on both banks of the channel near the tunnel.	Monitor leakage for clearness and quantity.
SLOPES	Spillway channel's side slopes are moderate. The channel that is cut through the rock, beyond the tunnel, has steep side slopes.	
APPROXIMATE NUMBER OF HOMES AND POPULATION	Both channels, mentioned above, meet approximately 1,000 feet from the spillway. The channel flows under Clinton Road, located about 1,300 feet from the spillway. One house is located on the channel's left bank approximately 1 mile from the spillway.	

CHECK LIST  
ENGINEERING DATA  
DESIGN, CONSTRUCTION, OPERATION

ITEM	REMARKS
PLAN OF DAM	Available at Manager's Office, City of Newark Department of Public Works, Division of Water Supply, 1294 McBride Ave., Little Falls, N.J. 07424
REGIONAL VICINITY MAP	Available-Passaic County Map and U.S.G.S. Quadrangle Sheet for Newfoundland, N.J.
CONSTRUCTION HISTORY	No formal history exists, but it can be deduced from available plans and drawings.
TYPICAL SECTIONS OF DAM	Available at Manager's Office (listed above)
HYDROLOGIC/HYDRAULIC DATA	None available.
OUTLETS - PLAN	Available at Manager's Office (listed above)
- DETAILS	Available at Manager's Office (listed above)
- CONSTRAINTS	None
- DISCHARGE RATINGS	Not available.
RAINFALL- RESERVOIR RECORDS	Available at Manager's Office (listed above)

CHECK LIST  
ENGINEERING DATA  
DESIGN, CONSTRUCTION, OPERATION  
(continued)

ITEM	REMARKS
DESIGN REPORTS	None available.
GEOLOGY REPORTS	Available U.S.G.S. Geologic Overlay Sheet for Passaic County and Engineering Soil Survey of New Jersey, Report No. 3--Passaic County by Rutgers University (New Brunswick, N.J.).
DESIGN COMPUTATIONS HYDROLOGY & HYDRAULICS DAM STABILITY SEEPAGE STUDIES	None available.
MATERIALS INVESTIGATIONS BORING RECORDS LABORATORY FIELD	None available.
POST-CONSTRUCTION SURVEYS OF DAM	None available.
BORROW SOURCES	Unknown.
SPILLWAY PLAN - SECTIONS - DETAILS	Available at Manager's Office (listed above)

CHECK LIST  
ENGINEERING DATA  
DESIGN, CONSTRUCTION, OPERATION  
(continued)

ITEM	REMARKS
OPERATING EQUIPMENT PLANS AND DETAILS	Available at Manager's Office (listed above)
MONITORING SYSTEMS	Water level indicator plans not available.
MODIFICATIONS	Valve House, constructed on top of embankment in 1960, drawings are available at Manager's Office listed above.
HIGH POOL RECORDS	Daily records have been kept since 1972.
POST CONSTRUCTION ENGINEERING STUDIES AND REPORTS	None known to exist.
PRIOR ACCIDENTS OF FAILURE OF DAM - DESCRIPTION - REPORTS	None known to exist.
MAINTENANCE OPERATION RECORDS	Kept since 1971.

APPENDIX B

PHOTOGRAPHS

(Taken on November 14 and December 4, 1979)

CLINTON RESERVOIR DAM



Photo 1 - View of downstream side of the embankment looking toward the spillway at the left end of the dam. Valve House and portion of reservoir are visible at upper left of photo. (Photo taken on November 14, 1979).




Photo 2 - View of embankment looking toward the spillway at the left end of the dam. Riprap is visible on the upstream side of the embankment. (Photo taken on November 14, 1979).

CLINTON RESERVOIR DAM



Photo 3 - View of reservoir from downstream, right side of dam. Valve House is at center right of photo. (Photo taken on November 14, 1979).



Photo 4 - View of embankment looking toward Valve House and right side of dam. The low level outlet channel, from Valve House, is visible at left center of photo. (Photo taken on November 14, 1979).

CLINTON RESERVOIR DAM



Photo 5 - View from Valve House looking downstream toward the low level outlet's channel. (Photo taken on November 14, 1979).



Photo 6 - View from the low level outlet channel looking upstream toward the tunnel under the embankment and the Valve House. Note channel cut out of rock. (Photo taken on November 14, 1979).



CLINTON RESERVOIR DAM



Photo 7 - View from the spillway's left abutment, in foreground, toward the embankment and right end of dam. (Photo taken on November 14, 1979).



Photo 8 - Detail of the spillway's right abutment wall. Note missing boulders and missing grout in the wall. (Photo taken on November 14, 1979).

CLINTON RESERVOIR DAM




Photo 9 - Detail of spillway looking toward the left abutment wall. Note crack in spillway. (Photo taken on November 14, 1979).



Photo 10 - View from the spillway looking toward the downstream channel. Photo taken on December 4, 1979).

APPENDIX C

SUMMARY OF ENGINEERING DATA

CHECK LIST  
HYDROLOGIC AND HYDRAULIC DATA  
ENGINEERING DATA

Name of Dam: CLINTON RESERVOIR DAM

Drainage Area Characteristics: 9.10 square miles

Elevation Top Normal Pool (Storage Capacity): 992 NGVD (10,796 acre-feet)

Elevation Top Flood Control Pool (Storage Capacity): N/A

Elevation Maximum Design Pool: 999.26 NGVD (SDF pool: 14,272 acre-feet)

Elevation Top Dam: 997.5 NGVD (13,372 acre-feet)

SPILLWAY CREST:

a. Elevation 992 NGVD

b. Type Broad crest weir

c. Width 300 ft.

d. Length 5.4 feet

e. Location Spillover Unknown. Water level was below spillway crest.

f. No. and Type of Gates None

OUTLET WORKS:

a. Type 4 - 42 inch C.I.P. pipes with 8,10,12, & 14 inch cone valves.

b. Location Right side of dam under valve (gate)house.

c. Entrance Inverts 950.3 NGVD

d. Exit Inverts 950 NGVD

e. Emergency Draindown Facilities 4 cone valves 8,10,12, & 14 inch dia.

HYDROMETEOROLOGICAL GAGES:

a. Type None


b. Location None

c. Records None

MAXIMUM NON-DAMAGING DISCHARGE: 10,448 cfs at elevation 997.5 NGVD.

APPENDIX D

HYDROLOGIC COMPUTATIONS



Scale: 1" = 1 Mile

CLINTON RESERVOIR DAM  
DRAINAGE BASIN

PRC Harris, Inc.  
CONSULTING ENGINEERS

SUBJECT NJ DAM SAFETY INSPECTION  
CLINTON RES.  
COMPUTED BY CLC CHECKED BY PK

SHEET No. 1 OF 9  
JOB No. 10-AB3-01  
DATE 3/2/80

GROUP XVII

SIZE CLASSIFICATION

Surface Area of Main Impoundment	405 Acres
Ave. Depth of Reservoir	40 ft
Structural Height of Dam	55.5 ft
Size Classification	Intermediate

HAZARD POTENTIAL CLASSIFICATION

Three Houses & 3 Heavily Travelling Roads  
Approximately One Mile D/S of Dam  
Hazard Potential Classification HIGH  
Recommended SDF PMF

HYDROLOGIC ANALYSIS

The HEC-1 DB will be used to route the Flood  
using SCS Triangular Unit Hydrograph with  
curvilinear Transformation

$$D.A. = 0.10 \text{ mi}^2$$

PRC Harris, Inc.  
CONSULTING ENGINEERS

SUBJECT NJ DAM SAFETY INSPECTION  
CLINTON RESERVOIR  
COMPUTED BY CLC CHECKED BY MLC

SHEET NO. 2 OF 20  
JOB NO. 10-AB3-01  
DATE 3/2/80

### PRECIPITATION

From fig. 15 (Ref. : 'Design of Small Dam', p. 48), the drainage basin located at the boundary between Zone 1 & Zone 6 where the Probable Max. Precipitation = 25 inches based on 6 Hrs. duration & a 10 sq. Mz. basin area.

<u>DURATION (HRS.)</u>	<u>% of PMF</u>		
	<u>ZONE 1</u>	<u>ZONE 6</u>	<u>AUG.</u>
6	99	100	100
12	111	109	110
24	119	117	118
48	127	126	127

Note: Values are reduced by 20% to account for misalignment of basin & storm isohyals.

### INFILTRATION DATA

Drainage Area Consists of Most of Sc, Mmg & E.  
(Reference "Engineering Soil Survey of N.J. - Passaic County, by Rutgers University")

Hydrologic Soil

:/0

Initial Infiltration

0.8 INCH

Const. Minimum Rate

0.08 IN/HR.



PRC Harris, Inc.  
CONSULTING ENGINEERS

SUBJECT N.J. DAM SAFETY INSPECTION  
CLINTON RESERVOIR  
COMPUTED BY CLC CHECKED BY BK

SHEET NO. 3 OF 9  
JOB NO. 10-A33-01  
DATE 3/3/80

### TIME OF CONCENTRATION

- 1) Estimating  $T_c$  from Velocity Estimating & Water Course Length :

	Slope	Vel.	Remarks
Overland Flow	$\frac{1420 - 1250}{520} = 0.33$	4.0	Woodlands
Channel Flow	$\frac{1250 - 1000}{17000} = 0.014$	1.5	

$$t_c = \left( \frac{520}{4} + \frac{17000}{1.5} \right) / 3600 = 3.18 \text{ Hrs.}$$

- 2) FROM NOMOGRAPH "Design of Small Dam"

$$\Delta H = 1420 - 980 = 440' \quad L = 18480'$$

$$T_c = 1.0 \text{ HR.}$$

- 3) USING F.A.A. FORMULA FROM SURFACE FLOW

$$T_c = \frac{1.8(1.1 - C)\sqrt{D}}{\sqrt{S}}$$

$$D = 18480'$$

$$C = 0.15 \text{ WOODED AREA}$$

$$S = \frac{440}{18480} = 2.38\%$$

$$\therefore T_c = 2.9 \text{ Hrs.}$$

PRC Harris, Inc.  
CONSULTING ENGINEERS

SUBJECT N. J. DAM SAFETY INSPECTION  
CLINTON RESERVOIR DAM  
COMPUTED BY C.L.C. CHECKED BY DA

SHEET NO. 4 OF 2  
JOB NO. 10-A83-01  
DATE 3/11/80

TIME OF CONCENTRATION (CONTINUED)

1) G. B. WILLIAMS FLOOD COMMITTEE

$$t = 0.908 L \sqrt[5]{\frac{L}{FD}}$$

Where  $t \sim$  time period in hrs.

$L \sim$  length of catchment in miles

$D \sim$  Diameter in miles of a circle having the same area

$F \sim$  catchment slope in %

$$t = 0.908 (5.3) \sqrt[5]{\frac{1}{(2.38)(3.56)}} = 3.14 \text{ HRS.}$$

$$\text{Use } T_c = 2.56 \text{ HRS.}$$

$$\text{LAG} = 0.6 T_c = 1.53 \text{ HRS.}$$

PRC Harris, Inc.  
CONSULTING ENGINEERS

SUBJECT N.J. DAM SAFETY INSPECTION  
CLINTON RESERVOIR  
COMPUTED BY CLC CHECKED BY RK


SHEET NO. 5 OF 59  
JOB NO. 10-A83-01  
DATE 3/3/80

## ELEVATION - AREA - CAPACITY RELATIONSHIP

Reservoir Storage values were obtained from water supply Division  
City of Newark

Elev.	950	951	960	965	970	975	980	985	990	991	992	993
	994	1000										
Storage Ac-Ft	0	25	1271	2246	3400	4744	6316	8009	10011	10404	10796	11189
	11587	14647*										

\* The value of Storage at Elev. 1000 was developed thru HEC-1 DB program




PRC Harris, Inc.  
CONSULTING ENGINEERS

SUBJECT N.J. DAM SAFETY INSPECTION  
CLINTON RESERVOIR DAM  
COMPUTED BY C.L.C. CHECKED BY B.K.

SHEET NO. 6 OF 60  
JOB NO. 10-A82-01  
DATE 3/11/80

OVERTOPPING POTENTIAL




OVERTOPPING OF DAM OCCURS AT E. 57%  
WITH  $Q = 10.448 \text{ cfs}$  ( $\sim 57\% \text{ PMF}$ )

FREDERIC R. HARRIS, INC.  
CONSULTING ENGINEERS

SUBJECT N.J. DAM SAFETY INSPECTION  
CLINTON RESERVOIR DAM  
COMPUTED BY G.L.C. CHECKED BY P.K.

SHEET NO. 7 OF 9  
JOB NO. 10-AB3-01  
DATE 3/6/80

DRAWDOWN TIME COMPUTATION




PRC Harris, Inc.  
CONSULTING ENGINEERS

SUBJECT N.J. DAM SAFETY INSPECTION  
CLINTON RESERVOIR DAM  
COMPUTED BY C.L.C. CHECKED BY ML

SHEET NO. 8 OF 9  
JOB NO. 10-A83-01  
DATE 3/6/80

DRAWDOWN TIME COMPUTATION (CONTINUED)

\_\_\_\_\_ EL. 992.0



8" 10" 12" 14" CIP

EL. 952.0

$$K_{entrance} = 0.5, K_{valve} = 0.1, K_{exit} = 1.0$$

$\epsilon = 0.00085$  and complete turbulence

$$\frac{\epsilon}{D_1} = 0.00128$$

$$f_1 = 0.0202$$

$$\frac{\epsilon}{D_2} = 0.00102$$

$$f_2 = 0.0198$$

$$\frac{\epsilon}{D_3} = 0.00085$$

$$f_3 = 0.0190$$

$$\frac{\epsilon}{D_4} = 0.00073$$

$$f_4 = 0.0184$$

$$\Sigma K = K_{entrance} + 2K_{reducer} + K_v + 2K_{increaser} + \frac{fL}{D} + K_{exit}$$

$$Q = A\sqrt{2gH} (\Sigma K)^{-\frac{1}{2}}$$

where A is based on 42"  $\phi$

$$\Sigma K_8 = 0.5 + 0.71 + 13.7 + 0.1 + 98.3 + 0.28 + \frac{0.0202(32)}{3.5} + 1 = 238.07$$

$$Q_8 = 5.0 \sqrt{H}$$

$$\Sigma K_{10} = 0.5 + 0.71 + 57.7 + 0.1 + 41.4 + 0.28 + \frac{0.0198(32)}{3.5} + 1 = 101.87$$

$$Q_{10} = 7.65 \sqrt{H}$$

$$\Sigma K_{12} = 0.5 + 0.71 + 27.0 + 0.1 + 19.5 + 0.28 + \frac{0.0190(32)}{3.5} + 1 = 49.26$$

$$Q_{12} = 11.0 \sqrt{H}$$

$$\Sigma K_{14} = 0.5 + 0.71 + 14.1 + 0.1 + 10.3 + 0.28 + \frac{0.0184(32)}{3.5} + 1 = 27.16$$

$$Q_{14} = 14.82 \sqrt{H}$$

$$Q = \Sigma(Q_8, Q_{10}, Q_{12}, Q_{14}) = (5 + 7.65 + 11 + 14.82) \sqrt{H} = 38.5 \sqrt{H}$$

DRAWDOWN TIME COMPUTATION (CONTINUED)

$$\text{Inflow} = 2 \text{ cfs} / \text{mi}^2 (9.1 \text{ mi}^2) = 18.2 \text{ cfs}$$

RES. EL.	Vol. Ac-ft	AVG. RES. EL.	Q 38.5 cfs	DRAW- DOWN TIME $\frac{24 \text{ Vol}}{1.82 \text{ Q}}$	Cul. Time (HRS)	DRAW- DOWN TIME W/ Inflow $1.82 \frac{Q}{Q}$	Cul. Time (HRS.)
992	785	991	240.4	39.6	39.6	3.0	42.6
990	2004	987.5	229.4	105.9	145.5	8.4	156.9
985	1688	982.5	212.6	96.2	241.7	8.2	261.3
980	1572	977.5	194.4	98.0	339.7	9.2	368.5
975	1344	972.5	174.3	93.5	433.2	9.8	471.8
970	1154	967.5	151.6	92.3	525.5	11.1	575.2
965	607	962.5	130.6	56.3	581.8	7.9	639.4
960	798	957.5	90.3	107.1	688.9	21.6	768.1
955	363	953.5	47.2	93.2	782.1	36.0	897.3
952							

A) Time of complete drawdown with no inflow = 782.1 HRS.  $\approx 33$  days

B) Time of complete drawdown with inflow (18.2 cfs) = 897.3 HRS.  
= 37 days.

N J DAM SAFETY INSPECTION PROGRAM-----GROUP XVII 10AB301  
 N J 00314 CLINTON RESERVOIR, PASSAIC COUNTY, NJ  
 MULTI RATIO ROUTING CASE 1, PRC-HARRIS INC., WOODBRIDGE, N J  
 0 20 0 0 0 4

LINE	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20
INFLOW HYDROGRAPH THROUGH CLINTON RESERVOIR																				
1	2	9	10	9	10	0	8													
25	100	110	118	127																
1	53																			
-	05	2																		
DAM																				
ROUTING DISCHARGE THROUGH DAM																				
1																				
23	473	1271	2246	3400																
10796	11189	11587	14647																	
951	955	960	965																	
992	993	994	1000																	
992	0	300	2.7	1.5																
997	5	2.60	1.5	1230																
99																				

10011 8004 6316 4744 3400 970 975 980 985 990  
 -992 0



N J DAM SAFETY INSPECTION PROGRAM-----GROUP XVII 10A0301  
 N J 00314 CLINTON RESERVOIR, PASSAIC COUNTY, NJ  
 MULT RATIO ROUTING CASE 1-PRC-HARRIS INC , WOODBRIDGE, N J

JOB SPECIFICATION									
NQ	NHR	NMTH	IDAY	INR	IMIN	MEIRC	IPLT	IFRT	NSTAN
150	0	20	0	0	0	0	0	4	0
			JOFFR	NMT	IKOPT	TRACE			
			5	0	0	0			

MULTI-PLAN ANALYSES TO BE PERFORMED

NPLAN= 1 NRATIO= 9 LRATIO= 1

KRLOS=	1.00	90	.80	.70	.60	.50	.40	.30	10
--------	------	----	-----	-----	-----	-----	-----	-----	----

\*\*\*\*\*

SUB-AREA RUNOFF COMPUTATION

INFLOW HYDROGRAPH THROUGH CLINTON RESERVOIR									
ISTAQ	ICOMP	IECON	ITAFE	JPLI	JPRI	INAME	ISTAGE	IAUTO	
LAKE	0	0	0	0	0	1	0	0	

HYDROGRAPH DATA									
IHYD	LUHG	TAREA	SNAP	IRSDA	IRSPC	KATIO	ISNOW	ISAME	LOCAL
1	2	9.10	0.00	9.10	.80	0.000	0	1	0

PRECIP DATA									
SFFE	FMS	K6	K12	K24	K48	K72	K96		
0.00	15.00	100.00	110.00	118.00	127.00	0.00	0.00		

LOSS DATA									
LRUFI	STNKK	BLINK	RTION	ERAIN	STNKS	RTION	STNKL	CNSIL	ALSHX
0.00	0.00	0.00	1.00	0.00	0.00	1.00	80	08	0.00

UNIT HYDROGRAPH DATA

TC= 0.00 LAG= 1.53

RECUSSION DATA

STK10= -1.00 KRCSN= -.05 RTIOR= 2.00

AD-A086 896

NEW JERSEY DEPT OF ENVIRONMENTAL PROTECTION TRENTON

F/G 13/13

NATIONAL DAM SAFETY PROGRAM. CLINTON RESERVOIR DAM (NJ 00314) P--ETC(U)

APR 80 J P TALERICO

DACW61-79-C-0011

NL

UNCLASSIFIED

2 OF 2

AD-A086 896



UNIT HYDROGRAPH 25 END OF PERIOD ORIGINATES, TC= 0.00 HOURS, LAG= 1.53 VOL= 1.00														
253. 781. 1658. 2370. 2443. 2073. 1539. 1068. 771.														
573. 414. 301. 219. 158. 84. 61. 44. 32.														
25. 18. 12. 7. 2.														
PMF														
END-OF-PERIOD FLOW														
MO. DA	HR. MN	PERIOD	RAIN	EXCS	LOSS	COMP Q	MO. DA	HR. MN	PERIOD	RAIN	EXCS	LOSS	COMP Q	
1.01	1.20	1	.00	0.00	.00	8.	1.02	1.20	76	.04	.01	.03	46.	
1.01	1.40	2	.00	0.00	.00	8.	1.02	1.40	77	.04	.01	.03	68.	
1.01	1.00	3	.00	0.00	.00	7.	1.02	2.00	78	.04	.01	.03	90.	
1.01	1.20	4	.00	0.00	.00	7.	1.02	2.20	79	.04	.01	.03	108.	
1.01	1.40	5	.00	0.00	.00	6.	1.02	2.40	80	.04	.01	.03	122.	
1.01	2.00	6	.00	0.00	.00	6.	1.02	3.00	81	.04	.01	.03	131.	
1.01	2.20	7	.00	0.00	.00	6.	1.02	3.20	82	.04	.01	.03	138.	
1.01	2.40	8	.00	0.00	.00	5.	1.02	3.40	83	.04	.01	.03	143.	
1.01	3.00	9	.00	0.00	.00	5.	1.02	4.00	84	.04	.01	.03	147.	
1.01	3.20	10	.00	0.00	.00	5.	1.02	4.20	85	.04	.01	.03	150.	
1.01	3.40	11	.00	0.00	.00	4.	1.02	4.40	86	.04	.01	.03	152.	
1.01	4.00	12	.00	0.00	.00	4.	1.02	5.00	87	.04	.01	.03	153.	
1.01	4.20	13	.00	0.00	.00	4.	1.02	5.20	88	.04	.01	.03	154.	
1.01	4.40	14	.00	0.00	.00	3.	1.02	5.40	89	.04	.01	.03	155.	
1.01	5.00	15	.00	0.00	.00	3.	1.02	6.00	90	.04	.01	.03	155.	
1.01	5.20	16	.00	0.00	.00	3.	1.02	6.20	91	.11	.08	.03	175.	
1.01	5.40	17	.00	0.00	.00	3.	1.02	6.40	92	.11	.08	.03	234.	
1.01	6.00	18	.00	0.00	.00	3.	1.02	7.00	93	.11	.08	.03	360.	
1.01	6.20	19	.01	0.00	.01	2.	1.02	7.20	94	.11	.08	.03	539.	
1.01	6.40	20	.01	0.00	.01	2.	1.02	7.40	95	.11	.08	.03	734.	
1.01	7.00	21	.01	0.00	.01	2.	1.02	8.00	96	.11	.08	.03	919.	
1.01	7.20	22	.01	0.00	.01	2.	1.02	8.20	97	.11	.08	.03	1076.	
1.01	7.40	23	.01	0.00	.01	2.	1.02	8.40	98	.11	.08	.03	1192.	
1.01	8.00	24	.01	0.00	.01	2.	1.02	9.00	99	.11	.08	.03	1273.	
1.01	8.20	25	.01	0.00	.01	2.	1.02	9.20	100	.11	.08	.03	1331.	
1.01	8.40	26	.01	0.00	.01	2.	1.02	9.40	101	.11	.08	.03	1374.	
1.01	9.00	27	.01	0.00	.01	1.	1.02	10.00	102	.11	.08	.03	1405.	
1.01	9.20	28	.01	0.00	.01	1.	1.02	10.20	103	.11	.08	.03	1428.	
1.01	9.40	29	.01	0.00	.01	1.	1.02	10.40	104	.11	.08	.03	1445.	
1.01	10.00	30	.01	0.00	.01	1.	1.02	11.00	105	.11	.08	.03	1457.	
1.01	10.20	31	.01	0.00	.01	1.	1.02	11.20	106	.11	.08	.03	1465.	
1.01	10.40	32	.01	0.00	.01	1.	1.02	11.40	107	.11	.08	.03	1472.	
1.01	11.00	33	.01	0.00	.01	1.	1.02	12.00	108	.11	.08	.03	1476.	
1.01	11.20	34	.01	0.00	.01	1.	1.02	12.20	109	.67	.64	.03	1620.	
1.01	11.40	35	.01	0.00	.01	1.	1.02	12.40	110	.67	.64	.03	2056.	
1.01	12.00	36	.01	0.00	.01	1.	1.02	13.00	111	.67	.64	.03	2979.	
1.01	12.20	37	.05	0.00	.05	1.	1.02	13.20	112	.80	.77	.03	4331.	
1.01	12.40	38	.05	0.00	.05	1.	1.02	13.40	113	.80	.77	.03	5873.	
1.01	13.00	39	.05	0.00	.05	1.	1.02	14.00	114	.80	.77	.03	7452.	
1.01	13.20	40	.06	0.00	.06	1.	1.02	14.20	115	1.00	.97	.03	8970.	
1.01	13.40	41	.06	0.00	.06	1.	1.02	14.40	116	1.00	.97	.03	10326.	
1.01	14.00	42	.06	0.00	.06	0.	1.02	15.00	117	1.00	.97	.03	11577.	

1.01	14.20	43	.08	0.00	.08	0	1.02	15.20	118	1.75	1.72	.03	12945.
1.01	14.40	44	.08	0.00	.08	0	1.02	15.40	119	4.79	4.76	.03	15339.
1.01	15.00	45	.08	0.00	.08	0	1.02	16.00	120	1.04	1.04	.03	18874.
1.01	15.20	46	.13	.08	.05	20	1.02	16.20	121	.93	.91	.03	23429.
1.01	15.40	47	.37	.34	.03	148	1.02	16.40	122	.93	.91	.03	26797.
1.01	16.00	48	.08	.05	.03	410	1.02	17.00	123	.93	.91	.03	27803.
1.01	16.20	49	.07	.04	.03	803	1.02	17.20	124	.73	.71	.03	27045.
1.01	16.40	50	.07	.04	.03	1144	1.02	17.40	125	.73	.71	.03	25095.
1.01	17.00	51	.07	.04	.03	1319	1.02	18.00	126	.73	.71	.03	22342.
1.01	17.20	52	.06	.03	.03	1354	1.02	18.20	127	.05	.03	.03	19619.
1.01	17.40	53	.06	.03	.03	1282	1.02	18.40	128	.05	.03	.03	17237.
1.01	18.00	54	.06	.03	.03	1127	1.02	19.00	129	.05	.03	.03	14714.
1.01	18.20	55	.00	0.00	.00	964	1.02	19.20	130	.05	.03	.03	11975.
1.01	18.40	56	.00	0.00	.00	828	1.02	19.40	131	.05	.03	.03	9399.
1.01	19.00	57	.00	0.00	.00	694	1.02	20.00	132	.05	.03	.03	7151.
1.01	19.20	58	.00	0.00	.00	534	1.02	20.20	133	.05	.03	.03	3311.
1.01	19.40	59	.00	0.00	.00	427	1.02	20.40	134	.05	.03	.03	3954.
1.01	20.00	60	.00	0.00	.00	318	1.02	21.00	135	.05	.03	.03	3003.
1.01	20.20	61	.00	0.00	.00	231	1.02	21.20	136	.05	.03	.03	2314.
1.01	20.40	62	.00	0.00	.00	166	1.02	21.40	137	.05	.03	.03	1803.
1.01	21.00	63	.00	0.00	.00	121	1.02	22.00	138	.05	.03	.03	1435.
1.01	21.20	64	.00	0.00	.00	88	1.02	22.20	139	.05	.03	.03	1313.
1.01	21.40	65	.00	0.00	.00	67	1.02	22.40	140	.05	.03	.03	1225.
1.01	22.00	66	.00	0.00	.00	63	1.02	23.00	141	.05	.03	.03	1143.
1.01	22.20	67	.00	0.00	.00	58	1.02	23.20	142	.05	.03	.03	1066.
1.01	22.40	68	.00	0.00	.00	54	1.02	23.40	143	.05	.03	.03	995.
1.01	23.00	69	.00	0.00	.00	51	1.03	0.00	144	.05	.03	.03	928.
1.01	23.20	70	.00	0.00	.00	47	1.03	0.00	145	0.00	0.00	0.00	866.
1.01	23.40	71	.00	0.00	.00	44	1.03	0.00	146	0.00	0.00	0.00	808.
1.02	0.00	72	.00	0.00	.00	41	1.03	1.00	147	0.00	0.00	0.00	754.
1.02	0.20	73	.04	.01	.03	38	1.03	1.20	148	0.00	0.00	0.00	704.
1.02	0.40	74	.04	.01	.03	36	1.03	1.40	149	0.00	0.00	0.00	656.
1.02	1.00	75	.04	.01	.03	34	1.03	2.00	150	0.00	0.00	0.00	612.
SUM										25.40	22.37	3.03	397757.
										( 645. )	( 568. )	( 77. )	(11263.22)

PEAK	6-HOUR	24-HOUR	72-HOUR	TOTAL VOLUME
27803.	17266.	5342.	2650.	397450.
787.	489.	151.	75.	11255.
	17.65	21.84	22.57	22.57
	448.31	554.84	573.32	573.32
	8562.	10596.	10949.	10949.
	10561.	13070.	13505.	13505.

CFS  
CMS  
INCHES  
MM  
AC-FT  
THOUS CU M

\*\*\*\*\*

HYDROGRAPH ROUTING

ROUTING DISCHARGE THROUGH DAM

ISTAG	ICOMP	IECON	ITAPE	JPLT	JFRT	INAME	ISTAGE	IAUTO
DAM	1	0	0	0	0	1	0	0
GLUSS	CLOSS	AVG	ROUTING DATA	IOPT	IPMP		LSTR	
0.0	0.000	0.00	1	1	0		0	
NSTPS	NSTDL	LAG	AMSKK	X	TSK	STORA	ISPRAT	
1	0	0	0.000	0.000	0.000	-992.	0	
0.	23.	473.	1271.	2246.	3400.	4744.	6316.	8004.
10404.	10796.	11189.	11587.	14647.				10011.
950.	951.	953.	960.	965.	970.	975.	980.	985.
991.	992.	993.	994.	1000.				990.
CREL	SPWID	COOW	EXPW	ELEVL	COOL	CAKEA	EXPL	
992.0	300.0	2.7	1.5	0.0	0.0	0.0	0.0	

DAM DATA  
TOPEL CUOD EXPD DAMWID  
997.5 2.6 1.5 1230.

PEAK OUTFLOW IS 23352. AT TIME 42.00 HOURS

PEAK OUTFLOW IS 20335. AT TIME 42.00 HOURS

PEAK OUTFLOW IS 17107. AT TIME 42.00 HOURS

PEAK OUTFLOW IS 13948. AT TIME 42.33 HOURS

PEAK OUTFLOW IS 10785. AT TIME 42.67 HOURS

PEAK OUTFLOW IS 8707. AT TIME 42.67 HOURS

PEAK OUTFLOW IS 6754. AT TIME 42.67 HOURS

PEAK OUTFLOW IS 4880. AT TIME 42.67 HOURS

PEAK OUTFLOW IS 1428. AT TIME 43.00 HOURS

